



Measure length, width, and height on your machine. Add 1" to each measurement to find your value for L, W, and H.

Cut:

- (2) L x H rectangles for the front & back
- (2) W x H rectangles for the sides
- (1) W x L rectangles for the top