



## Model XAD01/Z Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty	Unit	
001	266069-6	TAPPING SCREW 4X45	4	PC.	
002	317635-3	GEAR HOUSING	1	PC.	
003	227436-0	SPIRAL BEVEL GEAR 9	1	PC.	
004	210029-0	BALL BEARING 608ZZ	1	PC.	
007	227230-0	SPUR GEAR 29	1	PC.	
009	210033-9	BALL BEARING 696ZZ	1	PC.	
010	450607-6	GEAR HOUSING COVER	1	PC.	
011	803U04-5	CAUTION LABEL	1		
012	CB440	CARBON BRUSH CB-440 (195021-6)	1	SET	
014	539189-2	BRUSH HOLDER ASSY	1	PC.	
	D10	INC. 12			
015	619234-0	ARMATURE	1	PC.	
016	638613-3	YOKE UNIT	1	PC.	
017	187130-5	HOUSING SET	1	SET	
	D10	INC. 35			
018	266130-9	TAPPING SCREW BIND PT 3X16	5	PC.	
019	210029-0	BALL BEARING 608ZZ	1	PC.	
020	961052-5	RETAINING RING S-12	1	PC.	
021	227536-6	SPIRAL BEVEL GEAR 26	1	PC.	
022	211423-9	BALL BEARING 6806DDW	1	PC.	
025	285842-5	BEARING RETAINER 36-43	1	PC.	
026	763174-5	DRILL CHUCK S10	1	PC.	
027	254201-4	KEY 4	1	PC.	
028	631814-2	LED CIRCUIT	1	PC.	
029	689098-6	HEAT SINK	1	PC.	
030	911006-2	PAN HEAD SCREW M3X8	1	PC.	
031	632B91-1	SWITCH UNIT	1	PC.	
032	450610-7	F/R CHANGE LEVER	1	PC.	
033	450609-2	LINK	1	PC.	
034	450608-4	SWITCH LAVER	1	PC.	
035	187130-5	HOUSING SET	1	SET	
	D10	INC. 17			
036	815P23-9	XAD01 NAME PLATE	1		
037	644808-8	TERMINAL	1	PC.	
038	418036-9	GASKET	1	PC.	
A01	153489-2	GRIP 36 COMPLETE	1	PC.	
A02	251314-2	+ SCREW M4X12	1	PC.	
A03	450688-0	KEY HOLDER	1	PC.	
A04	763415-9	CHUCK KEY S10	1	PC.	
A05	***DC18RC	DC18RC FAST CHARGER	1	PC. (XAD01)	
A06	BL1830	BATTERY BL1830 SET	2	SET (XAD01)	
A07	450128-8	BATTERY COVER	1	PC. (XAD01)	
A08	141358-9	PLASTIC CARRYING CASE	1	PC. (XAD01)	
	C10	163455-1	LATCH	2	PC. (XAD01)
	C20	419360-3	HANDLE	1	PC. (XAD01)